

WV Meet Tour Itinerary

- From the meet location, drive north on US 119 to WV 601, take WV 601 north to US 60, cross US 60 at the traffic light for a vantage point to see construction of the new I-64 east bridge across the Kanawha River.
- Head back to US 60 west, turn left at approach to Dunbar Bridge (watch for a button copy overhead sign), cross bridge and turn right onto WV 25 east for a vantage point to see construction of the bridge on the opposite side of the river.
- Go west on WV 25 and take I-64 to Exit 40 for US 35.

The US 35 portion of the tour will be dependent on whether or not the highway is open to traffic. It may be open by the time of the meet. If so, we'll drive the route and stop periodically for photos. If the route is still not officially open, we'll follow this itinerary.

- Stop at the exit for WV 34. This is where the route currently ends; all US 35 traffic is forced onto the ramp for WV 34 and directed to turn right toward Winfield.
- Go under bridge on WV 34, turn right onto Poplar Fork Road (CR 13), then turn right onto Tucker Branch Road (CR 32). Proceed through the subdivision to new US 35.
- Go back to WV 34 and follow it to Winfield, turn left onto US 35 north, then turn left onto Hurricane Creek Road (CR 19). There is a Marathon station at the intersection. Take CR 19 to new US 35 for photos.
- Go back to US 35 north and turn left onto Johnston Drive (CR 35/29). Take CR 35/29 up to new US 35 and drive a portion of the unopened route, to 5 and 20 Mile Creek Road (CR 15) or Stave Branch Road (CR 24).
- Work our way toward the Buffalo Bridge (unsigned WV 869 and the end of the new US 35 construction) either by driving the unopened road or by going back to US 35 and going north to the bridge approach.
- Return to meet location via US 35, I-64 and WV 601.